From: Kelley Chase/R3/USEPA/US Sent: 2/29/2012 5:36:22 PM

To: Sgraves@TechLawInc.com
CC: Richard Rupert/R3/USEPA/US
Subject: RE: Dimock - Residential Well HW-47

Thanks Suddha. Just spoke with Fetzer - he confirmed that Cabot indicated that they did install an RO unit. Not sure when this was done. But it appears that this was prior to our sampling effort. I hope to get more info when I meet with the owner tomorrow. I will be sure to find out where the RO unit is located. Will let you know what I find out.

Thanks again- Kelley

From: "Graves, Suddha" < Sgraves@TechLawInc.com>

To: Kelley Chase/R3/USEPA/US@EPA
Cc: Richard Rupert/R3/USEPA/US

Date: 02/29/2012 03:40 PM

Subject: RE: Dimock - Residential Well HW-47

## Kelley,

Yes a sample was collected at the pressure tank and at the kitchen sink. I have no records which document the presence of a reverse osmosis unit at the series of the collection of the pressure tank and at the kitchen sink. I have no records which document the presence of a reverse osmosis unit at the series of the collection of the pressure tank and at the kitchen sink. I have no records which document the presence of a reverse osmosis unit at the series of the collection of the pressure tank and at the kitchen sink. I have no records which document the presence of a reverse osmosis unit at the series of the collection of the presence of the collection of the presence of the collection of the presence of the collection of

- There is an old well located near the house. This old well was not sampled.
- There was a water softener system in the basement. The "wellhead" sample was collected prior to this water softener system, while the "kitchen tap" sample was collected after this system.
- The residents noted that there is a sulfur smell present during their showers.
- The kitchen tap sample had a lot of effervescence and a slight sulfur odor.
- A propane tank (located outside of the home) was being filled during stabilization of the well.
- There is a small open drain in the basement.

The only reverse osmosis (RO) unit that I have documented is from HW-39 residence), which was sampled on 2/3/12. It was reported to have a low-flow faucet (1 gal/hour). A total metals sample (HW39-RO) was collected from this location (HW-39).

May I ask where you received the info that led you to believe the family had a RO system?

## Suddha Graves

TechLaw, Inc.

**From:** Kelley Chase [mailto:Chase.Kelley@epamail.epa.gov]

Sent: Wednesday, February 29, 2012 12:34 PM

**To:** Graves, Suddha **Cc:** Richard Rupert

Subject: RE: Dimock - Residential Well HW-47

Hi Suddha -

I will be meeting with the family tomorrow night along with several health professionals from ATSDR to answer questions about the high arsenic results. I wanted to double check a few things with you beforehand. I am guessing you will need to take another look at the sampler's logbook.

I understand that we collected a sample at the kitchen sink and at the pressure tank. Is this correct?

DIM0114656 DIM0114656

I have recently learned that the home has an reverse osmosis unit. This was not noted at the time of the original survey (which I conducted) or from what I can tell from your earlier e-mail - from the logbook. Is that correct? I want to be sure that I understand whether we collected a sample after the RO unit (if it exists)? It may have been installed to treat only drinking water from a separate low flow faucet (not the kitchen tap).

Thanks !!!

From: "Graves, Suddha" < Sgraves@TechLawInc.com >

To: Kelley Chase/R3/USEPA/US@EPA

Date: 02/15/2012 10:42 AM

Subject: RE: Dimock - Residential Well HW-47

Kelley,		
HW47 was sampled on 2/8/12.	Ex. 6 - Personal Privacy	Dimock. Well is reported to be
450 feet deep, with 178 ft of casing, an	d it is unknown what the depth of the pump is. Wate	r had a slight sulfur smell and was
slightly effervescent. There was a press	sure tank and water softener in basement. It was note	ed that there was sewer gas at the
home		

The following screening results were collected:

## Wellhead

Alkalinity 193 mg/L Dissolved Sulfide 0.087 mg/L Ferrous Iron 2.71 mg/L Turbidity 1.4 NTU

## **Kitchen Sink**

Alkalinity 194 mg/L Dissolved Sulfide 0.038 mg/L Ferrous Iron 0.01 mg/L Turbidity 0.22 NTU

If you want, I have photos and scanned copies of logbooks and field data sheets.

Thanks,

Suddha Graves

TechLaw, Inc.

From: Kelley Chase [mailto:Chase.Kelley@epamail.epa.gov]

Sent: Wednesday, February 15, 2012 8:44 AM

To: Graves, Suddha

Subject: Dimock - Residential Well HW-47

Hi Suddha -

I am sending this now - so that I don't forget to ask you later.

Based on the preliminary results - we have elevated arsenic (90s ug/L) in the samples collected from HW-47.

From the well survey info collected by EPA we know the following:

- well appox 450' deep, well approx 40 yrs old, original pump
- have a softener and chlorinator (installed in the 70s)
- there are also 2 other wells on the property (one deep which is used for irrigation and one shallow hand dug well)

DIM0114656 DIM0114657

I would appreciate it if you could check the field logs for any additional information noted by the sample team. It would be helpful if I could get this info by noon.

Thanks - Kelley

DIM0114656 DIM0114658